

Delco Carburetor

BULLETIN 9D-201

DATE: NOVEMBER, 1971

PAGE 1

FILE IN SERVICE "FIX" SECTION

SERVICE INFORMATION

SUBJECT:

New Screw Kit Released for Monojet Carburetors

PART NUMBER:

7041830 - Screw Kit

A new kit is released which contains self-locking type screws for use on Monojet carburetors.

The following screws are contained in the kit:

- 1 Fast idle cam screw
- 3 Long air horn screws
- 3 Short air horn screws
- 2 Throttle body to bowl attaching screws
- 2 Air cleaner bracket screws

The special screws in the kit have self-locking threads and are extremely useful on applications where excessive engine vibration or rough road operation can cause loose carburetor screws.



Todachie Centrator

Transport and a transport

SERVICE INFORMATION

House and with responsible not supported that the page and

Diverse description of the property of the

The state of the second of the state of the state of the state of the second of the state of the

Tal Will be beforedood, and arrested and the life

Debath care, project and

surrect ascella infinial a final

NAMES THE PARTY OF

care of product of bond attended for voice

NAMED TO BE OF THE PARTY OF THE PARTY.

and the second state of the second strength and and are second as a second seco

AR CONTACTOR CONTACTOR

CUE BURREY WINDOWS DOORS.



PART NO. 7041342

DELCO CARBURETOR SERVICE INFORMATION

SUBJECT: Quadrajet Secondary Main Well Seal

BULLETIN 9D- 202

1

DATE November, 1971

PAGE

FILE IN 9D-200 SECTION

NO.

Some cases of fuel leakage at the secondary main well plugs have been reported on early model quadrajets.

If leakage occurs past the two plugs, it will fill the secondary well cavity in the throttle body with fuel. The fuel then seeps through the throttle body-to-bowl gasket, and into the carburetor bores which could result in rough idle or hard starting.


To stop this seepage of fuel, a special Viton* seal is available for service use only. Use of this seal avoids the possibility of cracking the bowl when installing some types of plugs available on the market.

The procedure for installing this seal is as follows:

- 1. Remove carburetor from engine.
- 2. Disconnect accelerator pump rod.
- 3. Remove float bowl-to-throttle body attaching screws and two long air horn attaching screws at rear of carburetor and remove throttle body.
- 4. Insert seal, part #7041342, into bottom of secondary well cavity in throttle body, see figure below.
- Replace throttle body to float bowl, tightening attaching screws and two air horn screws evenly and securely.
- Reconnect accelerator pump rod and install carburetor on engine.

NOTE: The two secondary well plugs should not be removed when performing this operation.

*Registered trade-mark E.I. duPont deNemours



(OSS - 0051) CO:9, 131, 132:G-K, FD, WD, X DELCO CASBULETOR

Defermed productions of the same

STATE FROM STREET AND STREET

25.00

The state of the s

the state of the first of the f

beernigt to well after our action wit affind out the "and Material" to 1900 to appear it it to 1900 to

idealitatives of trees with posteriors with a furnition of a re-

- Animal-mark restaurance assume E
- 2. Died in expeliential paper in the
- The first that the pool and the policy published by the property of the policy of the
- The public of statement of statement of the property of the property of the public of
 - Asserting through bothy for their book.
 - Tele-189 televis totaleten Laurenstill July in television distribution
 - Startiff make the watercook out a 17 of 1000 printed the factor investors and 1000



STRUMBERS OF THE CONTRACTOR

Service of the servic



DELCO CARBURETOR

SUBJECT: Quadrajet - Stripped Fuel Inlet Nut Repair

BULLETIN 9D- 203

DATE January, 1974

PART NO. 7041634 and 7041635

PAGE 1 of 2

FILE IN 9D-200 SECTION

NO. 74-T-1

REPLACES 9D-203

DATED November, 1971

Two fuel inlet adapter repair kits are released to cover all Quadrajet models. Applications are as follows:

Kit Part No.

Use on Following Quadrajet Applications

7041634

1966-71 Buick* 1966-71 Oldsmobile

1967-71 Pontiac


1965-71 Chevrolet - 3/8" fuel line

*On 1966 Buick use the original inlet nut with nipple adapter

7041635

1967-71 Cadillac

1966-67 Chevrolet - 5/16" fuel line



INSTALLATION INSTRUCTIONS ON REVERSE SIDE

INSTALLATION OF FUEL INLET ADAPTER

- 1. Remove fuel inlet nut, filter and spring and discard all parts.
- Blow out fuel inlet cavity in float bowl making sure it is free of chips and foreign material.
- 3. Apply Loctite Primer "T" to threaded area of bowl and on inlet nut adapter. Allow Primer "T" to dry on threads.

Note: The use of Loctite adhesive #75 and "T" Primer is to assure a permanently sealed fitting in the carburetor bowl and no attempt should be made to remove adapter.

IMPORTANT

Loctite Primer "T" and #75 adhesive sealant is available through parts jobbers and dealers.

4. Install one inlet nut gasket on adapter. Coat the threads of adapter which fit into float bowl with Loctite #75. Use extreme caution so Loctite is only on adapter threads.

Note: On 1966 Model 4MV carburetors the fuel passage end plug retainer should be used if needle and seat Modification Kit #7036775 has been installed.

- 5. Install adapter in bowl and torque to 50 ft. lbs.
- 6. Blow out bowl cavity by blowing air through adapter.
- Install new filter spring, filter and inlet nut with gasket.
 Note: Care should be taken when installing inlet nut, filter and gasket not to move adapter as it takes 5 to 10 minutes for Loctite to set up.
- 8. Connect fuel line.
- Adjust engine to specified R.P.M.



SUBJECT: SERVICE REPLACEMENT IDLE

LIMITER CAPS

PART NO. All Carburetors

BULLETIN 9D-204

DATE November, 1973

PAGE 1

FILE IN 9D-200 SECTION

NO. 74-I-2

Replaces 9D-204 dated April, 1972

Special attention is directed to vehicle manufacturer's recommendations for idle speed and idle mixture adjustments. Complete effectiveness of the Exhaust Emission Control system, on vehicles so equipped, depends upon idle speed and idle mixtures being set to factory specifications.

The idle mixture is preset and sealed at the factory with black plastic limiter caps. The idle mixture caps should not be removed in the field unless idle mixture adjustment is required after cleaning or major carburetor repair. If the idle needle caps are removed the idle mixture should be reset according to instructions on the decal in the engine compartment or as outlined in the service manual.

Red plastic limiter caps were originally used for replacement after field adjustment and were supplied separately and in the repair kits. The red limiter cap replacement is no longer required after field adjustment, so they have been discontinued as a replacement part.



SUBJECT:

MONOJET CARBURETOR CHOKE SHAFT

AND LEVER REPLACEMENT

PART NO.

All 1968 and later Monojet carburetors

BULLETIN 9D- 205

DATE August, 1972

PAGE 1

FILE IN 9D-200 SECTION


NO. 72-T-1

All 1968 Monojet carburetors have a slot in the fast idle cam to allow free movement of the choke rod in the cam. The upper choke rod lever has a standard hole for attachment of the upper end of the choke rod to the choke shaft.


If choke shaft replacement is necessary, it should be serviced with choke shaft and lever assembly, Part No. 7034009. The upper choke rod lever is still serviced separately under Part Number 7034056.

On 1969 and later models the upper choke lever is slotted for free movement of the choke rod and the fast idle cam has a standard hole. On these models a choke shaft and lever kit, Part No. 7036973, must be used if necessary to replace the upper choke rod slotted lever or the choke shaft and coil lever assembly.

The new kit, Part Number 7036973, contains a choke shaft with the slotted choke lever spun on one end and a separate choke coil rod lever with an attaching screw.



1968 Models



1969 and later models

(OSS - 0519) CO, WD, 131, 132: 16, 9X, 9FR, 9FD, 9LA

PRINTED IN U.S.A.

© GENERAL MOTORS CORP.



BELCO CARBULLTOR

AVELECT: HEHOLET CARBURETOR CHOKE SHAFT

commenced and 1968 and large Monojet corouteters.

BULLETIN BO: 201 DATE: August, 1972

PALE OF SECTION

All [958 Beng]et corburators have a slot in the fast interior chose close of the common of the cook of the control the copier chose rod lever has a stangerd hole for ottochmost of the opper end of the choice rod to the choice shaft.

of choice shaft replacement is necessary, it chould be stricted on choice chaft choice searchly. Part No. 7034009. The upper choice out lever in still serviced separately under Part Number 7034036.

On 1969 and later models the upper choke lever in slotted the free novement of the choke rod and the fast idle can has a standard hole. On these models a choke shoft and laver kit; Part No. 7050913, wast be used if necessary to replace the upper choke rod slotted lever or the choke shaft and coil lever assembly.

The new bir, Part Number 7036973, containers choke shaft with the slutted choke lever spun on one and and a separate choke Coli rod lever with an attaching screw.



A Laborate State Lin



a labour marged has solded

255 - 0819) 0 WO 131 138116 DX 855 850 814

A 2.0 m ostalan .-: NDOS SESTON MANNES ©

SALENS JELES

CA TRAS

45



SUBJECT:

Monojet Main Well Plug Kit

BULLETIN 9D- 200

PART NO.

7041848 Assortment Kit

DATE January, 1974

PAGE 1 of 2

FILE IN 9D-200 SECTION

NO. 74-I-1

Replaces 9D-200

Dated November, 1971

The	assortm	nent	kit	has	been	relea	sed	to	the	field	for
repla	cement	of	the	main	well	plug	whe	ere	neces	ssary.	The
folio	wing are	cor	taine	d in th	ne kit:						

Quantity	Part No.	Identification	Color
10	7030470	No bleed hole	Silver
5	7030471	.023" bleed hole	Silver
5	7030472	.030" bleed hole	Copper
10	7030473	.036" bleed hole	Black

Some plugs have bleed holes and some do not.

It is very important that the correct plug be used in each particular carburetor model. The following list gives the correct plug application for each carburetor unit:

1968		1969		1970	
Carb.	Plug	Carb.	Plug	Carb.	Plug
No.	Color	No.	Color	No.	Color
7028006	Black	7029007	Silver (no hole)	7040007	Silv. (bld. hole)
7028007	Black	7029008	Black	7040008	Black
7028008	Black	7029011	Silver (no hole)	7040011	Silv. (bld. hole)
7028009	Black	7029012	Silver (no hole)	7040012	Silv. (no hole)
7028010	Black	7029014	Silver (no hole)	7040014	Silv. (no hole)
7028011	Black	7029015	Silver (no hole)	7040017	Silv. (no hole)
7028012	Black	7029017	Silver (no hole)	7040021	Silv. (bld. hole)
7028013	Black	7029021	Silver (no hole)	7040022	Silv. (no hole)
7028014	Black	7029022	Silver (no hole)	7040025	Silv. (bld. hole)
7028015	Black	7029047	Silver (bleed hole)	7040026	Silv. (no hole)
7028017	Black	7029057	Black		
7028047	Silver (bleed hole)	7029165	Copper		
7028057	Black	7029166	Copper		
7028065	Silver (bleed hole)	7029167	Copper		
7028067	Copper	7029168	Copper		
7028082	Black				
7028083	Black				
7028180	Black				
7028181	Black				
7028182	Black				


1971		1972		1973	
Carb. No.	Plug Color	Carb. No.	Plug Color	Carb. No.	Plug Color
7041014 7041017 7041021 7041022 7041023 7041024 7041025 7041026	Silver (bleed hole) Silver (bleed hole) Silver (bleed hole) Silver (no hole) Copper Copper Silver (bleed hole) Silver (no hole)	7042011 7042012 7042014 7042017 7042021 7042022 7042023 7042024 7042025 7042026 7042984 7042987 7042991 7042992 7042993	Silver (bleed hole) Silver (no hole) Silver (bleed hole) Silver (bleed hole) Silver (bleed hole) Silver (bleed hole) Copper Copper Copper Silver (bleed hole) Copper	7043009 7043012 7043014 7043017 7043021 7043022 7043023 7043024 7043025 7043026 7043312 7043323 7043324 7043326 7043333	Silv. (bld. hole) Silv. (no hole) Silv. (bld. hole) Copper Copper Silv. (bld. hole) Silv. (no hole) Silv. (bld. hole) Copper Copper Copper Silv. (bld. hole) Copper Copper Silv. (bld. hole) Copper
		7042994 7042995	Copper Silver (bleed hole)	7043334	Copper

Installation:

The main well plug is a press fit and is located in top of main well as shown. To install use a tool made from a piece of 5/16" steel gas line tubing cut to 3" length. The inside diameter of gas line is approximately 1/4". If a piece of regular tubing is used, make sure the inside diameter is the above dimension. Remove burrs from end of tube.

- 1. Remove carburetor from engine; then remove air horn assembly from float bowl.
- 2. Start new main well plug into top of main well with fingers. Make sure sides of plug are vertical with hole in main well.
- Using the 3" piece of 5/16" steel gas line and hammer, carefully drive main well plug inward until bead on plug rests on top of main well casting. SEE DRAWING.

CAUTION: Do not use any type sealer on main well plug as it may get into fuel channels.





SUBJECT: CORRECT INSTALLATION OF FLOAT NEEDLE

PULL CLIP

PART NO. All Quadrajet Carburetors

BULLETIN 9D- 206

DATE August, 1972

PAGE 1


FILE IN 9D-200 SECTION

NO. _____72-T-2

Reports have been received of incorrect installation of the float needle pull clip on the float arm during field replacement. If the clip is not installed as recommended, carburetor flooding can result.

It is reported that the end of the pull clip is being installed through the holes in the top of the float arm above the needle. These are locating holes used for manufacture of the float arm and are <u>not</u> to be used for the pull clip.

Correct installation of the float needle pull clip, is to hook the clip over the edge of the flat on float arm facing the float pontoon, as shown.



Note: The only exception to this is when using the float needle modification kit - Part Number 7036775. This needle pull clip hooks over the opposite edge of float arm as shown on instruction sheet in the kit.

(OSS - 0519) CO, WD, 131, 132: 16, 9X, 9FR, 9FD, 9LA

PRINTED IN U.S.A.
© GENERAL MOTORS CORP.

residential believes the low they

TOTAL DORUGE BY BANK


(1)

negers have been repelled of incherent legicalistics of the filet incherent field replacement. It is not the front con during flight replacement it confine to the filet of the committee of the filet it confine to the filet of the committee of the filet of the filet of the committee of the filet of the f

to the interest of that the eve of the out) offin is being inhighted the through the holes for the tipe of the floridate of the floridate of the floridate and the floridate of the floridate of

three a least the edge of the fine the files, benefits and a least the files the files of the files and files and files and files are files and files and files and files are files are files and files are files are files and files are files are files and files are files are files are files and files are files and files are fi

HOOSE BLANCOUR BUILDING



marks.

The only entages for the city bender with the star of the public head to be the public bender the city bender the city of the

n 250 ne departures.

Mile (NISS - ZEO)



SUBJECT:

PUMP ROD REMOVAL ON ROCHESTER

QUADRAJET CARBURETORS

PART NO. All 1970 and later models

BULLETIN 9D~ 207

DATE August, 1972

PAGE

FILE IN 9D-200 SECTION


NO. 72-T-3

The above model carburetors use a clipless pump rod to prevent the possibility of retaining clips being accidentally left off or becoming lost due to improper installation.

Reports have been received that the pump rod is being bent to remove the rod from upper pump lever when removing the air horn from float bowl. This is a bad safety practice as the pump rod will be weakened and also may cause a bind due to not being aligned properly after bending.

Correct removal of the pump rod should be done by driving the small roll pin retaining the upper pump lever inward (towards air cleaner boss) until the lever can be removed from boss on air horn. Then remove upper pump lever, pump rod and air horn assembly.

To install pump rod after air horn installation, install pump rod to throttle lever and upper end of rod to upper pump lever. Then insert upper lever into boss on air horn and push roll pin back through hole in pump lever until the outer end of pin is flush with boss on air horn. See sketch.



(OSS - 0519) CO, WD, 131, 132: 16, 9X, 9FR, 9FD, 9LA

TO SLOVE

PUMP RED REMOVAL ON ADDRESSES.

sieben much bas Over the con years

BUILLITH BD- 26 BATE August, 1877 PAGE 1

HOPTOSO COS-DE MI MATE

The above model carborstors use a clipiess pump rodults prevent the possibility of reselving alies being accidentally left of becoming test due se increment installation.

Reports have been received that the pump rod is being bent to remove the rod from upper pump lever when removing the air horn from float bowl. This is a bed safety practice as the pump rod will be weakered and also may cause a bind due to not heing aligned properly after and also may cause a bind due to not heing aligned properly after and headless.

Correct removal of the pump rod should be done by driving the shall roll plantestations the upper pump lever launed (towards air clanner costs) with the lever can be removed from buss on air hors. Then remove

To install pump red ofter all horn installation, install pump red to the theoretical lever. Then insurt theoretical lever and upper end of red to upper pump lever. Then insurt upper lever into boss on all horn and push roll pin back through hole in pump lever until the outer and of pin is fluck with boss on all horn.

DATIVE PIN HIMLARD TO REPOVE PUMP LEVER



(0.22 0.919)

COMMISSYMPT RESIDENCE TO SECURE CO.



SUBJECT: QUADRAJET AIR VALVE CAM REPLACEMENT

BULLETIN 9D- 209

PART NO. 7035344 Air Valve and Spring Kit

DATE August, 1972

PAGE

FILE IN 9D-200 SECTION

NO. 72-I-2

A cam and spring kit is available for Quadrajet air valve cam repair. The kit includes the cam, spring, set screw, pin, and the air valve shaft seal plug.

To replace cam:

1. Remove air valve screws

2. Remove air valves

3. Remove set screw for adjustment pin

4. Remove adjustment pin

5. Remove wind-up spring

6. Drive out air valve shaft

7. Install new cam

8. Reverse above procedure for re-assembly

9. Install new shaft seal

10. Refer to specification for setting air valve wind-up. (Bulletin 9D-210)

(OSS - 0588) CO:9, 131, 132:G-K, WD, FD, X PRINTED IN U.S.A.

© GENERAL MOTORS CORP.

DELCO CARRUSTICATOR

THE DESCRIPTION OF THE BOX OF THE PARTY OF T

- wd _______w

A com and aprino kit is available for Guadrajet air valuo can repair. The Mit includes the came tering, set screw, plin, and the air value coult seal plus.

Stight smallten of

The said of the state below it.

estilia in avail a

mig from the low with the second to

Lottle brand subtantion avoids in

THE PARTY OF THE COURSE OF THE PARTY OF

Section of the section of the section of

syley, nin, girlfank not on the little of the little

AND STREET

FUEL SYSTEM



DELCO CARBURETOR SERVICE INFORMATION

BULLETIN 9D- 209 SUBJECT: QUADRAJET AIR VALVE CAM REPLACEMENT

> DATE August, 1972

PART NO. 7035344 Air Valve and Spring Kit

PAGE

FILE IN 9D-200 SECTION

NO. ___72-I-2

A cam and spring kit is available for Quadrajet air valve cam repair. The kit includes the cam, spring, set screw, pin, and the air valve shaft seal plug.

To replace cam:

1. Remove air valve screws

2. Remove air valves

3. Remove set screw for adjustment pin

4. Remove adjustment pin

5. Remove wind-up spring

6. Drive out air valve shaft

7. Install new cam

8. Reverse above procedure for re-assembly

9. Install new shaft seal

10. Refer to specification for setting air valve wind-up. (Bulletin 9D-210)

(OSS - 0588)CO:9, 131, 132:G-K, WD, FD, X

AID WALVE



DELCO CARBURETOR SERVICE INFORMATION

SUBJECT:

Air Valve Windup Setting Procedure and

Specifications.

PART NO.

All Quadrajets


BULLETIN 9D- 210

DATE November, 1973

PAGE 1 of 2

FILE IN 9D-200 SECTION

NO. <u>72 - 1 - 3</u> Replaces 9D-210 Dated August, 1972



AIR VALVE SPRING ADJUSTMENT

MODEL	YEAR	CARBURETOR NO.	WINDUP (TURNS)
Buick	' 66	ALL	5/8
	'67-'69	ALL	1/2
	770-772	ALL	7/16
	773	7043240-242-243	7/16
		7043244	11/16
	′74	7044240-241-540	7/16
		7044242-244-246-248-544-546	11/16
Cadillac	'67	ALL	1/4
	' 68	7028230-231	1/2
		7028234-235	7/16
	' 69	ALL TO THE STATE OF THE CONTROL OF THE STATE	1/2
	770	ALL:	7/16
	71-72	ALL	1/2
	773	7043230-231-233	5/16
		7043232	3/8
	'74	7044230-233-235-530	3/8
		7044232-532	1/2
		7044234	5/16
Chevrolet	'65-'66	ALL	1
-9. W	' 67	ALL	7/8
	' 68	7028207-208-212-219-229	3/8
		/28209-210-211-213-216-217-218	7/8
	'69	7029200-204-207-214-215	13/16
		7029201-202-203-223	7/16

(OSS - 0051) CO:9, 131, 132:G-K, FD, WD, X (OVER)

PRINTED IN U.S.A.

© GENERAL MOTORS CORP.

MODEL	YEAR	CARBURETOR NO.	AIR VALVI WINDUP (TURNS)
Chevrolet Cont'd.	′70	7040200-202-203-208-213-500-502-503-508 7040511-512-513	7/16
	NATION.	7040201-204-205-206-207-221-501-504-505 7040506-507- 509-52 1	13/16
	'71	7041200-201-202-203-204-205-208-209-211 7041212-213	7/16
	A A DESCRIPTION	7041206 SUIAMILE OF SUIAMILE O	13/16
	72	7042200-201-204-205-209-212-215-216-217 7042218-219-220	7/16
		7042202-203-208-210-211-902-903-910-911	1/2
		7042206—207	11/16
	73	7043200-201-207	11/16
		7043215-502-503-508-510-511-515	1/2
		7043212-213-217-224-512-513	1 1
	17.4	7043202-203-210-211-219	3/4
	'74	7044202-203-206-207-213-214-215-216-218-219 7044224-502-503-506-507-513-514-515-516	7/8
		7044518—519	
		7044201-212-217-221-223-225-227-505-512 7044517-520-550	7/16
		7044208-209-210-211	1
Oldsmobile	'66	704226-526-527	3/4
Olusinophe	00	7026250-256-7036250	3/4
		7026254—7036254 7026255	1/2
	'67		5/8
	07	7027156-157	3/4
	['] 68	7027036–135–153 7028250	1/2
	00	7028251-252-255	1/2
	'69	7029250	3/4
	03	7029251-252-253-254-255	1/2
	770	7040251-252-253-255-256-257-258-551-552	3/4
		7040554—555 7040250—550	3/4
	771	7041-252-253-257	
		7041250	3/4 1/2
	72	7042251-252-951-952-953	3/4
		7042250-950	1/2
	73-74	7043250-255-256-257	1/2
		7043251-252-253-254-258-259	3/4
	'74	7044557-558-559	3/4
Pontiac	'66-'69	ALL PROPERTY OF THE PROPERTY O	1/2
	′70	7040577	3/8
		7040262-263-264-267-268-271-274-275-276 7040277-562-563- 564 -567-568-572-575-576	7/16
		7040265-266-270-273-565-566-570-573	3/4
	771	7041267-268-270	1/2
		7041262-263-264-271	7/16
	′72	7042262-270-273	7/16
		7042264	5/8
		7042267	9/16
		7042263	11/16
	′73	7043263	5/8
		7043265-274	9/16
		7043262-272	3/8
		7043264	1/2
	′74	7044262-267-272-560	3/8
		7044266-268-269-568	1/2
		7044270—273	3/4
		7044274	9/16



SUBJECT: USE OF INCORRECT THROTTLE BODY TO

FLOAT BOWL GASKET - QUADRAJET

PART NO. 1970 and Later Quadrajet Carburetors

BULLETIN 9D- 211

DATE November, 1972

PAGE

FILE IN 9D-200 SECTION


NO. 72-I-4


Field reports, along with returned samples, indicate servicemen sometimes are substituting the wrong throttle body to float bowl gasket on 1970 and later model Quadrajet carburetors. When this substitution is made, vacuum leaks occur causing rough idle due to air by-passing the primary throttle valves through the canister purge passage in the throttle body because the gasket will not seal this passage.


Therefore, in no case should the wrong throttle body to float bowl gasket be used on 1970 and later model Quadrajet carburetors.

The difference between the throttle body to bowl gaskets is shown below:









PRINTED IN U.S.A.

© GENERAL MOTORS CORP.



HOLITHIANA CONTO

TO SUCK SHIP TO SHIP TO SUCK TO SUCK TO SUKE

MCMODE des grate and


Field charts, along onth Edulined Semples, indicate sets compared to a set of the compared to a set of the control of the cont

Therefore, in no case should the principal bidly to floor has notice by the body of the floor has been provided to the state of the body o

Telegraph of the contract the contract in the contract of the

administration and a depletion of the second

BOARD BURLE HETEROLE WILLIAM



e e u un generate. En e a energia de a antique de



SUBJECT: "LOADED" QUADRAJET FLOATS

BULLETIN 9D- 212

PART NO. 1967-70 BUICK, CHEVROLET AND

DATE March, 1973

PONTIAC QUADRAJET

PAGE

FILE IN 9D-200 SECTION

NO. 73-T-1

Some cases of loaded float assemblies have been encountered in the above Quadrajet carburetors.

If after setting the idle speed to specified R.P.M., main discharge nozzle drip or excessive stalling is encountered, especially on stops, check the float level setting. If float setting is 0.K., check for a float "loaded" with fuel.

If the float pontoon has absorbed fuel it will feel heavier than a new float of the same part number or will sometimes show wetness when squeezed between the thumb and finger. If these conditions are found, replace the float assembly.

STATE OF THE PROPERTY OF THE P

Street of the product of the street of

did temperature about on-take Lon trans

COLUMN STAR STAR

have a triggering regard and a special property to be a server and a s

of ter beichng the tate speed this principal fluid A.P.A. Maint at a charge note of extending the endenthand. I achieve the total fluid being the second second of the sec

If the first potential has chartest that in an il feet bravier than a most front of the case cardinalists of all congresses than a most front to the congress between the trunc and finger.

If there conditions are flowed, confiden the floor accessiv.

MET ST ST TEN

WINDSHIP AND ESCON ON THE

A Septim consess.

\$100 and the second of the second of



不 -



DELCO CARBURETOR SERVICE INFORMATION

SUBJECT: VAPOR CANISTER - PURGE VALVE REPAIR

PART NO. 7041344 PURGE VALVE REPAIR KIT

BULLETIN 9D- 213

DATE March 1973

PAGE 1

FILE IN 9D-200 SECTION

NO. ____73-I-1

The purge valve located on the top of the fuel vapor collection canister, used on some applications, can be repaired without replacing the complete vapor canister. (See photo)

The repair kit, Part No. 7041344, consists of the following:

1 - Diaphragm cover


1 - Diaphragm

1 - Spring Retainer Washer

1 - Diaphragm Spring

Service of the purge valve is not a routine maintenance item and should be performed if damaged or parts are missing.

Install parts in order shown in photo. Make sure spring is seated in metal retainer and diaphragm lays flat between purge valve flange on canister and diaphragm cover. Snap diaphragm cover in place aligning vacuum pick-up tube with vacuum hose.





ROTHBURRAS OS RO FOLLANDOS MESONAL

distribution about - repaired notay trained to

THE HANGE SURVEY SHOW WELLOW! THE PARTY

HOTELSTEEN STREET STREET

The outing valve logated on the 100 of the fuel vapor collection cindister, used on some applicantions, can be repaired without replacing the obsolute vapor canisher (See photo)

The cession of the Part No. 700 Sent Connected

(Dispire and dover

s all assists agrees and to exist a

testal paret in order shown in photos. In Maintene upring is spaced in metal retainer and disphreym lays bint between our drivalve florge on consister and confron cover. Only dispute a state to

A ROY OF THE REAL PROPERTY.

EDDY SAPLE

John Color Age Triban

A SECRETAR PROPERTY OF THE PROPERTY OF THE PARTY OF THE P



SUBJECT: REMOVAL OF CLIPLESS PUMP PLUNGER ASSEMBLY FROM INSIDE PUMP LEVER

PART NO. ALL MODEL 2GV (2 BARREL) CARBURETORS USING INSIDE RETAINING LEVER

BULLETIN 9D- 214

DATE APRIL 1973


PAGE 1

FILE IN 9D-200 SECTION

NO. ____73-I-2

When removing the pump plunger assembly from the inner pump lever on those models not using a retaining clip, it is necessary to first remove the inner pump lever from the pump shaft by loosening set screw on inner lever. Then remove inner pump lever from pump shaft. Rotate pump plunger assembly until upper end of plunger rod slips out of hole in inner pump lever.

CAUTION: Do not remove pump plunger assembly by bending the retaining arm on inner lever. If bent, the retaining arm can cause binding, jamming and in some cases, allow the pump assembly to fall out of the lever.





HOTE MEDICAL TOPAS

THE REPORT OF THE PERSON OF TH

AND THE PROPERTY OF THE PROPER

TOTAL TOTAL STATE

then come ing the bein studger detailed from the tends .

The least on these dealers due neither a state of the state of t

TION: On now reading game, plantiful message to be been to a time the recording binds of binds of the read to the particular to the particular to the particular to the time of the time of the particular to the time of the particular to the time of the particular to the

MAY WILL LITERATE WALLOW THAN

A DOMESTIC OF THE STATE OF THE

THE RESERVE OF THE PARTY OF THE



SUBJECT: QUADRAJET CARBURETOR SECONDARY MAIN

WELL SEAL

PART NO. 7041342

Reference Service "Fix" Bulletin 9D-202 dated November 1971.

BULLETIN 9D- 215


DATE July, 1973

PAGE 1

FILE IN 9D-200 SECTION

vo 73-1-3

Field reports indicate servicemen are replacing the float bowl assembly and/or adding secondary main well plug seal 7041342 in the throttle body cavity (see illustration below), on Quadrajet carburetors that use the solid aluminum "spun-in" secondary main well plugs, to correct what appears to be "leaking secondary main well plugs". The presence of fuel in the cavity actually is due to "weeping action" whereby fuel from the secondary nozzles, during engine operation, seeps by the throttle body to bowl gasket to partially fill the cavity in the throttle body. Fuel in the throttle body cavity below the "spun-in" main well plugs will not affect operation and the float bowl assembly should not be replaced or the secondary main well plug seal 7041342 used.



If leakage of fuel at the secondary main well plugs is suspected, place the bowl on the bench on a dry, clean towel and fill the bowl with fuel. After about 5 minutes, carefully lift the bowl checking for dampness on the towel in the secondary main well plug location. If leakage is evident, the 7041342 seal may be installed in the throttle body cavity.

(OSS - 0401) 132:K,9WD,9X,9FD



tornautika oane

SUBJECT QUADRAJET CARBURETOR SECRIDARY MALK


PARTAGE TON THE

Reference Service "Fix" bulletin 30-202

BULLETIN SD- 210
DAGE-1
PAGE-1
PAGE-1

PILE OF TO PEO SECTION

First property indicate servicemen are replacing the floor book established and for serving section serving seal 704/342 in the shrinks budy could establish budy could see illustration below), on Quadrajet carbonators that the the solid standard "sounding "sounding securdary main well plugs", the presence of total in the cavity securding securdary main well plugs". The presence of total in the cavity securdary operation, seeps by the throatile body so bout suches to partially fill the cavity in the throatile body, finel in the throatile body cavity below the "spunding well well and a throatile body cavity below the "spunding well well and a standard and the file for the securdary main well plugs will not affect operation and the files body cavity main well plugs will not affect operation and the files bow exemptor main well plugs seed or the secondary main well plug seed for the secondary main well



If impliance fuel as the secondary main well plugs to suspected, place the bowl sold bench on a dry, class coupl and fill the bowl sitts fuel, after about 5 minutes, carefully lift the bost checking for dampeau on the track in the secondary main well plug location. If lookage in evident, the 70h13h2 read may be installed in the throttle body cavity.

(05\$ - 040T) 1323C, PWD, PX, FFD

A C U III GETRINA ...



Service Bulletin

Bulletin 9D-216

Date November, 1974

Page one 74-T-1

File in 9D-200 Section

SUBJECT: Quadrajet Secondary Main Well Plug Seal Kit 17052246


The secondary main well plug repair kit is released for use on early model carburetors which use the brass cup plug or solid aluminum plug without spinning. This kit should not be used on later models with the "spun-in" type secondary main well plug.

Before installing plug kit, check for leaks as follows:

- 1. Disassemble carburetor.
- 2. Place float bowl on stand and fill half full of fuel.
- 3. Observe plug area for fuel seepage.
- 4. In plugs leak, remove early type brass cup plugs with "Easy-out". If plug is solid type (without spinning), use a 3/16" stop drill and drill hole 1/4" deep in center of old plug. Use "Easy-out" and remove plug.

CAUTION: Do not drill through plug as casting may be damaged in well area. Blow out casting to remove dirt and chips.

5. Install rubber "0" ring seal into groove in new plug. Lube assembly with light engine oil, then carefully drive plug into main well, chamfered end down. Top of plug should be flush with casting. Lightly stake in place.



INSTALLATION
SECONDARY MAIN WELL PLUGS

A transfer his wilding size that it calls a long still the sale in the

Delco Carburetor Service Bulletin

Bulletin 9D-217

Date 12/1/76 Page 1 of 5

Page 1 of 5 No. 76-I-1

FILE IN 9D-200 SECTION

SUBJECT: IDLE MIXTURE ADJUSTMENT PART NO. ALL 1977 G.M. VEHICLES

Idle mixture screws have been preset at the factory and capped. Do not remove the caps during normal engine maintenance.

Before suspecting the carburetor as the cause of poor engine performance or rough idle, check ignition system including distributor, timing, spark plugs and wires. Inspect air cleaner, evaporative emission system, EFE system, PCV system, EGR system, and engine compression. Also inspect intake manifold, vacuum hoses and connections for leaks and check torque of carburetor mounting bolts/nuts.

In the case of major carburetor overhaul, throttle body replacement or high idle CO as indicated by state or local emission inspection, then idle mixture may be adjusted. Adjusting mixture by other than the following method may violate Federal and/or California or other state or Provincial laws. The following procedure MUST be followed.

PROCEDURE

- 1. Set parking brake and block drive wheels. On cars equipped with a vacuum parking brake release, disconnect and plug vacuum hose at brake.
- 2. Remove air cleaner for access to carburetor, but keep vacuum hoses connected. On cars with automatic level control, disconnect and plug vacuum hose to compressor.
- 3. Disconnect and plug other hoses as directed on Emission Control Information Label under the hood.
- 4. Engine must be at normal operating temperature, choke open, air conditioning off.
- 5. Connect an ACCURATE tachometer to engine.
- 6. Disconnect vacuum advance and plug hose, check ignition timing. If necessary, adjust to specification shown on Emission Control Information Label. Reconnect vacuum advance.


NOTE: On cars with electronic spark timing, follow instructions on Emission Control Information Label very carefully.

- 7. Carefully remove caps from idle mixture screws. Be careful not to bend screws. Lightly seat screws, then back out EQUALLY just enough so engine will run.
- 8. Place transmission in *Drive (automatics) or Neutral (manuals).
 - Except certain trucks. See Emission Control Information Label.
- 9. Back each screw out (richen) 1/8 turn at a time until maximum idle speed is obtained. Then set idle speed screw to value shown in Chart Column A. See specs page 3 thru 5. Repeat Step 9 to be certain you have maximum idle speed.
- 10. Turn each screw in (lean) with 1/8 turn increments until idle speed reaches value shown in Chart Column B. (See specs. pages 3-5).
- 11. Reset idle speed to specification shown on Emission Control Information Label. (Note: This number may be different than the value shown on Chart Column B).
- 12. Check and adjust fast idle as described on the Emission Control Information Label.
- 13. Reconnect vacuum hoses. Install air cleaner.
- 14. Recheck idle speed. If necessary reset to specification.

1977 ENGINE IDENTIFICATION

When performing service on 1977 General Motors passenger cars, it is often necessary to know the size and the source of the engine. This information is readily available by referring to the vehicle identification number. This number is in the left corner of the dash and is visible through the windshield. It also appears on a tag on the rear edge of the left front door. The fifth character in the vehicle identification number identifies the engine.

VEHICLE IDENTIFICATION NUMBERS



Following is a list of engine code letters for 1977. It gives the size of the engine and the division that manufactures the engine.

VIN CODE	ENGINE SIZE	SOURCE
В	140 in. 4 cyl.	Chevrolet
С	231 in. V-6	Buick
D	250 in. L-6	Chevrolet
E	98 in. (1.6L) 4 cyl.	Chevrolet
F boort ettresti	260 in. V-8	Oldsmobile
H	350 in. (2 bbl.) V-8	Buick
Did Park	05:- /1 41 \ 4 1	Chevrolet
J	350 in. (4 bbl.) V-8	Rujek
K	403 in. V-8	Oldsmobile
L	350 in. V-8	Chevrolet
P	350 in. V-8	Pontiac
R	350 in. V-8	Oldsmobile
S	425 in. V-8	Cadillac
T	425 in. V-8 EFI	Cadillac
U	305 in. V-8	Chevrolet
V	151 in. 4 cyl.	
X	350 in. V-8	Chevrolet
Υ	301 in. V-8	
Z	400 in. V-8	Pontiac
	IDLE MIXTURE ADJUSTMEN	ITS

ABBREVIATIONS - (Terms):

EFI Electronic Fuel Injection

M/T Manual Transmission
A/T Automatic Transmission
A/C Air Conditioning

High Altitude — Engines calibrated for elevations over 4000 feet above sea level.

Federal - Engines calibrated for all states except California.

California - Engines calibrated to meet California emission requirements.

When performing idle mixture adjustments -

- 1. Identify engine
- 2. Follow idle mixture adjustment procedure as outlined on page 1.
- 3. Set to specifications that follow.